

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 11303

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080134-5

RECEIVED FROM

DATE REC'D. 2-13-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS	
									ACCEPTED	REJECTED		
5	NOTED											
		732173	But Roller							4	1	RET#3642
			(Orig. 322-0-12-0-22)									
			IPS #65935									

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11314

RECEIVED FROM

DATE REC'D. 2-13-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS	
									ACCEPTED	REJECTED		
4	322		67	A	22							
		732167	Shaft Asbly Shuffler							4		
			Shipper #85939									

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080134-5